

Back Injuries Are Expensive

WE ALL KNOW THAT

But did you know?

80% of patient falls happen inside the bathroom.¹

PROBLEM

The world's best power stretcher **can't** save your back here.



Back injuries from improper patient lifting is the number one injury suffered by EMS personnel.²

FACT

It is **impossible** to lift properly without having handles attached to the patient.



Despite the invention of the power cot the EMS industry has a lifting related injury rate **21x** the national average.³

SOLUTION

The Binder Lift secures up to 25 handles to the patient so caregivers can effectively **team lift** with proper ergonomics.



1. National Institute on Aging (NIA), Preventing Senior Falls, 2012
2. Pena L. EMS Continuing Education Guide For Licensed Personnel and Continuing Education Coordinators. New Mexico Department of Health EMS Bureau, April 2007
3. Maguire BJ, Hunting KL, Guidotti TL, Smith GS, The Epidemiology of Occupational Injuries and Illnesses Among EMS Personnel. Prehospital Emergency Care. 2005; 9: 405-411

"Your device is one of three on my crews' most favorite list along with, Ferno Stair Chairs, and Stryker Power Pro Gurneys. They believe each of these devices are adding years to their backs holding up. Thanks for a great product."

- Joseph M. Repar,
Central Kitsap
Fire & Rescue

BINDER LIFT™



BINDER LIFT™



Models:

NYLON: Made from Cordura nylon and polypropylene webbing

VINYL: Made from BondCote vinyl and Biothane webbing

Sizes:

STANDARD: 34" – 62" circumference

BARIATRIC: 58" – 82" circumference

Vinyl Binder Lift Shown



Cushioned top edge for patient comfort

Patented torso wrap design provides patient stability and reduces risk of skin tears, bruising, and fractures

Removable leg straps for superior versatility

19-25 handles allow for multiple caregivers to team lift while using proper ergonomics

5 YEAR WARRANTY

MADE IN USA



Why Go Another Shift With Your Back At Risk?